

CONTENTS

	PAGE
PREFACE	v
FIRST AID TO A GOOD MILLINER.	xi

UNIT I

HAND-BLOCKED AND DRAPED FELTS AND STRAWS; WITH DRAPED CRINOLINE MODELS

1. HEADSIZE BAND—A PREREQUISITE FOR ALL MILLINERY.	3
2. HAND-BLOCKED FELT CROWNS.	7
3. HAND-BLOCKED FELT BRIMS—WORKED FROM EDGE TO HEADSIZE—STRAIGHT SEAM.	12
4. HAND-BLOCKED FELT BRIMS—WORKED FROM HEADSIZE TO EDGE—NO SEAM.	17
5. HAND-BLOCKED FELT OR STRAW BRIMS—WORKED FROM EDGE TO HEADSIZE—WHEN BRIM IS CUT AND LAPPED.	19
6. HAND-BLOCKED FELT OR STRAW BRIMS—WORKED FROM EDGE TO HEADSIZE—WHEN BRIM IS TO BE PLEATED, AND WHEN BLOCK IS NOT CARVED TO INDICATE PLEATS	21
7. DRAPED CRINOLINE BRIMS—WITH CRINOLINE CUT CIRCULAR—PINNING THE SEAM AFTER DRAPING (PREPARATORY TO DRAPING FELT OR STRAW).	24
8. DRAPED CRINOLINE BRIMS—WITH CRINOLINE CUT CIRCULAR—PINNING THE SEAM BEFORE DRAPING (PREPARATORY TO DRAPING FELT OR STRAW).	34
9. DRAPED CRINOLINE BRIMS—WITH BIAS CRINOLINE (PREPARATORY TO DRAPING FELT OR STRAW)	38
10. DRAPED FELT OR STRAW BRIMS—ACCORDING TO CRINOLINE MODELS OR FINISHED HATS	43
11. FELT OR STRAW BRIMS STRETCHED ON PATTERNS—WHEN USING FLANGES FROM HOODS OR BODIES.	49
12. HAND-BLOCKED STRAW CROWNS	53
13. HAND-BLOCKED STRAW BRIMS—WORKED FROM EDGE TO HEADSIZE—STRAIGHT SEAM	55
14. HAND-BLOCKED STRAW BRIMS—WITHOUT SEAMS—WORKED FROM HEADSIZE TO EDGE.	59

UNIT II

FINISHING PROCESSES

15. MEASURING, CUTTING, AND JOINING TRUE AND LONG BIAS STRIPS—A PREREQUISITE FOR ANY JOB USING A BIAS	63
16. A QUARTER-INCH BIAS BINDING	67
17. A QUARTER-INCH BINDING—WITH RIBBON ONE-HALF INCH WIDE—WITH BOTH SELVAGES SHOWING	71
18. A QUARTER-INCH BINDING—WITH RIBBON THREE-QUARTERS INCH WIDE—WITH ONE SELVAGE SHOWING.	75
19. A CIRCULAR RIBBON FLANGE—WITH HALF-INCH BELTING RIBBON	79
20. A CIRCULAR RIBBON FLANGE—WITH ONE AND ONE-HALF INCH BELTING RIBBON—ON A STEEL WIRE—ON A BLOCK—PLACED ON A BRIM OR EXTENDING.	83
21. PLAIN FOLDS	86
22. MILLINER'S FOLDS	90
23. A FINISHED CORD ON A WIRE—SEWED TO A BRIM—SUGGESTIONS FOR A FINISHED CORD ON A CABLE CORD AND FOR AN UNFINISHED CORD.	92

UNIT III

FRAME MAKING—BRIMS

24. HAND-MOLDED BRIMS—BIAS—ON HEADSIZE OR ON CROWNS.	99
25. MAKING BRIMS WITH PATTERNS	103
26. MAKING BRIMS—FREE HAND—STRAIGHT	106

	PAGE
27. WIRE FRAMES—BRIMS	108
28. MODEL FRAMES—BRIMS	113
29. STRETCHED BRIMS—FITTED	117
30. STRETCHED BRIMS—BIAS	121
31. TAKING A PATTERN FROM A BRIM	123

UNIT IV

COVERING BRIMS

32. BIAS TOP FACING—RAW EDGE—FINISHED	129
33. BIAS UNDER FACING—RAW EDGE—ON A WIRE—SLIPSTITCHED—IN ONE WITH BINDING	132
34. STEAMED DOUBLE FACING—BIAS—WITH SUGGESTIONS FOR USING IT AS A BRIM—A CORONET—A LOOSE FLANGE	136
35. FITTED TOP FACING—WITHOUT SEAM—FAIRLY REGULAR SHAPES	141
36. FITTED TOP FACING—WITH SEAM—IRREGULAR SHAPES	144
37. FITTED UNDER FACING—WITHOUT SEAM—FAIRLY REGULAR SHAPES—RAW EDGE—ON A WIRE—SLIPSTITCHED	148
38. FITTED UNDER FACING—WITH SEAM—IRREGULAR SHAPES—RAW EDGE—ON A WIRE—SLIPSTITCHED	150

UNIT V

CROWNS

39. STEAMED CRINOLINE FOUNDATION CROWN—ONE PIECE	155
40. CUTTING PAPER PATTERNS FOR VERTICAL SECTION CROWNS—FROM TIP TO HEADSIZE OR WITH PLAIN SIDE CROWN	158
41. VERTICAL SECTION CROWNS—SUGGESTIONS FOR CORDING AND MAKING SECTIONAL TIP	161
42. STEAMED TIP—FITTED SIDE CROWN—SUGGESTIONS FOR DRAPING SIDE CROWN	170
43. STEAMED TWO-PIECED FOUNDATION CROWN OF CRINOLINE—ON REGULATION BLOCK—ON BLOCK THAT IS LARGER AT THE TIP THAN AT THE HEADSIZE	174
44. CUTTING AN OVAL TIP PATTERN—WHEN ONLY THE HEADSIZE MEASUREMENT IS GIVEN—WHEN THE DIAMETERS OF THE HEADSIZE ARE GIVEN	177
45. TIP AND SIDE CROWN—STITCHED BY MACHINE—SOFT—NOT STEAMED—PLAIN—DRAPED—EVEN ROWS OF STITCHING	180
46. SHIRRED CROWNS—ON SMALL TIPS—WITH AND WITHOUT WIRE OR CORD—WITH NO TIPS—PLAIN OR FULL SIDE CROWNS	184
47. COPYING AND DESIGNING CROWN PATTERNS FOR SIDE-TO-SIDE SECTION CROWNS—SUGGESTIONS APPLIED TO ANY TYPE CROWN	191
48. MAKING A CROWN WITH SIDE-TO-SIDE SECTION PATTERNS	197
49. RIBBON CROWNS WORKED AROUND—OF NO. 16 RIBBON	201
50. RIBBON CROWN WORKED VERTICALLY FROM CENTER OF TIP TO BOTTOM OF CROWN—SUGGESTIONS FOR USING FOLDS IN THE SAME WAY	206

UNIT VI

COLLAPSIBLE HATS

51. SOFT BRIM—BY PATTERN—WITH EVEN ROWS OF MACHINE STITCHING—SUGGESTIONS FOR A LOOSE FLANGE—FITTED	213
52. GETTING A SHAPED HEADSIZE LINE ON A BLOCK—PREPARATORY TO MAKING TURBANS, OR BERETS (TAMS)	220
53. FOUNDATIONS FOR TURBANS OR BERETS (TAMS)—MALINE—TAFFETA—CRINOLINE	222
54. SUGGESTIONS FOR RIBBON HATS	225
55. BERETS (TAMS)—THE VERTICAL SECTION TYPE—THE TIP AND SIDE CROWN TYPE	228
56. HOW TO MOUNT BERETS (TAMS)	234
57. REGULATION DRAPED TURBAN	238

UNIT VII

TRANSPARENT HATS

	PAGE
58. STEAMED MALINE BRIM OVER A WIRE FRAME	247
59. STEAMED MALINE FLANGE—SUGGESTIONS FOR USING FLANGE AS A BRIM—SUGGESTIONS FOR STEAMING LACE.	251
60. STEAMED MALINE CROWN.	255
61. HAIR-BRAID BRIMS—PLAIN AND ROLLED EDGE.	258
62. HAIR-BRAID CROWNS—ANY CROWN WORKED FROM HEADSIZE TO TIP.	261

UNIT VIII

STRAW WORK

63. STRAW BRIMS—SEWED OVER A MODEL FRAME USING FOUR- OR FIVE-ROW BRAID	267
64. STRAW CROWNS—SEWED OVER A BLOCK USING FOUR- OR FIVE-ROW BRAID	273
65. STRAW BRIMS USING WOVEN BRAID—EITHER OVER A PATTERN, OR MODEL FRAME, OR BLOCK, OR RIGHT ON A FRAME.	277
66. STRAW CROWNS OF WOVEN BRAID—RIBBON CROWNS WORKED FROM THE TIP DOWN	281

UNIT IX

RENOVATIONS

67. SUGGESTIONS FOR RENOVATING AND REMODELING HATS.	285
---	-----

UNIT X

LININGS

68. CAP LINING	293
69. FRENCH OR OPEN LINING	298
70. RIBBON BAND OR FOLD—USED AS A LINING (SWEAT BAND)	303
APPENDIX.	307
INDEX	311

